

GPIB

USB

LAN

7481/7482 Digital Multimeter

8½-digit high-precision and high-accuracy digital multimeter for system calibration

- 8½-digit display (119 999 999), 0.01 ppm resolution DC voltage measurement: 100 mV to 1000 V, 10 nV resolution DC current measurement: 100 nA to 1000 mA, 100 fA resolution Resistance measurement: 10 Ω to 1000 M Ω , 1 $\mu\Omega$ resolution AC voltage/current, frequency and period measurements (7482 only)
- High-accuracy measurement by self-calibration function
 5 ppm/year (DC voltage measurement relative accuracy)
 8 ppm/year (resistance measurement relative accuracy)
 Auto-calibration of frequency characteristics for AC voltage measurement (7482 only)
- Internal memory storage up to 50,000 data (or 500,000 data for the Option +06)
- High-speed sampling up to 50,000 readings/s





https://www.adcmt.com

DMM for System Use with High Accuracy

The 7481/7482 is an 8¹/₂-digit digital multimeter with high resolution of 0.01 ppm, equipped with DC voltage, DC current and resistance measurement functions. It is suitable for use in research and development fields or calibration organizations, and calibration of inspection systems for electronic components or semiconductors.

The 7481/7482 achieves high-resolution measurement such as 10 nV for DC voltage measurement, 100 fA for DC current measurement and 1 $\mu\Omega$ for resistance measurement, and also guarantees high relative accuracy 5 ppm per year

for voltage measurement and 8 ppm per year for resistance measurement. The 7482 also has AC measurement capability, and AC voltage measurement can be made from 10 Hz to 2 MHz using the True RMS method.

In addition, the self-calibration function allows high-accuracy measurement at any time, and external calibration can be performed with a smaller number of standards.

The 7481/7482 comes standard with GPIB and USB interfaces for automated systems, and LAN is available as an option. It is designed with rear input terminals for system integration.

8¹/₂-digit high-performance DMM suitable for high-accuracy measurement

The 7481/7482 is a high-performance digital multimeter with $8\frac{1}{2}$ -digit display for DC voltage or resistance measurement (119 999 999) and $7\frac{1}{2}$ -digit display for DC current measurement (11 999 999). As high-resolution DC voltage ratio measurement is also possible, this is the best used as standard and for high-accuracy measurement.

	7481/7482			7482			
	DC voltage	Resistance	DC current	DC voltage ratio	AC voltage	AC current	Frequency/Period
Maximum display	119 999 999	119 999 999	11 999 999	999 999 999	1 199 999	1 199 999	9 999 999
Relative accuracy*	0.5 + 0.1	2 + 0.2	5 + 10	1.25 + 0.25	150 + 150	300 + 200	100
(Condition)	10 V range	$10 \ k\Omega$ range	1000 µA range	10 V range	10 V range 1 kHz	1000 µA range 1 kHz	Gate time 1 s

*Relative accuracy: ±(ppm of reading + ppm of range), Tcal ± 1 °C, 24 hours


All you need to perform external calibration for the 7481/7482 are two sources: a DC voltage standard (10 V) and a resistance standard (10 k Ω).

By the two-source calibration and the self-calibration function, all ranges of voltage, current and resistance are calibrated and internal errors due to ambient temperature change can be removed. As a result, high-accuracy measurements are guaranteed. Calibration values are stored in the internal memory together with their calibration date, and these data can be read out by the GPIB, USB or optional LAN.

High-precision A/D converter

The 7481/7482 adopts a self-developed multi-slope integration system for A/D conversion. So, it realizes high-precision linearity and excellent stability as standard, making it possible to perform high-accuracy measurements.


The following figure shows the stability at 0 V input in the 10 V range.



Low-noise design

The 7481/7482 offers measurement with less dispersion by its low-noise ranging amplifier.

The following figure shows the integration time and effective values (rms) of display dispersion at 0 V input in the 100 mV range.



Various Functions Convenient for Measurements

High-precision resistance measurement by thermal EMF cancellation

The 7481/7482 has a high-precision resistance measurement function in which micro thermal electromotive force that causes errors in resistance measurement is cancelled automatically.

4-wire contact check function

In 4-wire resistance measurement, contact check on the current source and voltage measurement points are performed. Measurement errors due to wrong connection or contact failure can be judged in advance.

Auto-calibration of frequency characteristics (7482 only)

In AC voltage measurement, the frequency characteristics of the input section attenuator are automatically calibrated by calibration signals generated from the internal reference voltage, enabling measurement with good frequency characteristics.

50,000 data internal memory

50,000 (or 500,000 data for the Option + 06) measurement data can be stored in the internal memory (RAM) at high speed up to 50,000 samples per second.


Front/rear input terminal external control

The front and rear input terminals can be controlled externally via the GPIB, USB or optional LAN.

It can prevent switching errors between the front and rear input.

Ratio measurement function

In ratio measurement, the reference DC voltage is measured by using the 4 W Ω measurement terminal in addition to normal DC voltage measurement, and its voltage ratio is gained by calculation. Using this function, it is possible to measure attenuator voltage division ratio and electric power, eliminating error factors of the external supply source in resistance measurement.




Comparator function

Efficient PASS/FAIL judgement is available by setting threshold values for inspection of electronic components such as resistors and semiconductors. Judgment results PASS or FAIL are displayed as measurement results on the screen, and also are output to the COMPARATAOR output terminal.

Statistic operation function

The maximum 50,000 (or 500,000 for the Option +06) samples can be set. Statistic operation results such as maximum value, minimum value, average, dispersion and standard deviation (σ) are displayed.



7481/7482 Specifications

DC Voltage Measurement

Range/maximum display/resolution/input impedance

Danga	Maximum			Inputimpedance			
Range	display	8 1⁄2	7 ½	6 ½	5 ½	4 1⁄2	Input impedance
100 mV	119.99999 mV	-	10 nV	0.1 µV	1 µV	10 µV	>100 GΩ
1000 mV	1199.99999 mV	10 nV	0.1 µV	1 µV	10 µV	100 µV	>100 GΩ
10 V	11.9999999 V	0.1 µV	1 µV	10 µV	100 µV	1 mV	>100 GΩ
100 V	119.999999 V	1 µV	10 µV	100 µV	1 mV	10 mV	10 MΩ±1 %
1000 V	1099.99999 V	10 µV	100 µV	1 mV	10 mV	100 mV	10 MΩ±1 %

Maximum input voltage: Input HI-LO ±1000 Vpeak GUARD-chassis ±420 Vpeak GUARD-LO terminal ±100 Vpeak

Accuracy: Relative accuracy with the integration time of 100 PLC ± (ppm of reading+ ppm of range)

Range	24 hours ^{*2}	90 days [™]	1 year ^{'3}	
nange	Tcal ^{*1} ± 1 °C		Tcal ± 5°C	
100 mV	2.5+10	5.0+10	7.0+10	
1000 mV	1.5+1	4.0+1	6.0+1	
10 V	0.5+0.1	3.0+0.2	5.0+0.2	
100 V	2.5+1	5.0+1	7.0+1	
1000 V	2.5+0.1	5.0+0.2	7.0+0.2	

*1 Tcal = temperature at calibration (23 °C)

*2 4 minutes or more after range switching (MATH NULL, fixed range), Tcal ± 1 °C

*3 Within 24 hours after last INT CAL, ± 1 °C, Tcal ± 5 °C (MATH NULL, fixed range)

INT CAL: internal calibration (calibration of errors in DMM)

Add 0.9 ppm of reading additional error for ADC traceability to Japan's national standard.

Voltage coefficient: Add 7 ppm (Vin/1000 V)² for 100 V or higher input. Temperature coefficient: ± (ppm of reading + ppm of range)/°C

Danga	Temperature coefficient			
Range	Without INT CAL	With INT CAL		
100 mV	1.2+1	0.25+1		
1000 mV	1+0.1	0.15+0.1		
10 V	1+0.01	0.15+0.01		
100 V	1.2+0.1	0.25+0.1		
1000 V	1.2+0.01	0.25+0.01		
100 V	1.2+0.1	0.25+0.1		

Without INT CAL: INT CAL is not performed regardless of the ambient temperature change

With INT CAL: INT CAL is performed according to the ambient temperature change and a measured value right after that is used.

Temperature coefficient additional error with	Range	Additional error ppm of range/°C
Auto-zero OFF	100 mV	50
	1000 mV/100 V	5
	10 V/1000 V	1

Additional error: Add the following additional errors for integration time other than 100 PLC.

Additional errors by integration time ^{*4}

Integration time	Gain error ppm of reading	Range error ppm of range
2 µs to 5 µs	2000	1000
6 µs to 10 µs	1000	500
20 µs to 100 µs	200	100
200 µs to 1 ms	30	20
2 ms to 10 ms	10	10
1 PLC	1	0.6
2 PLC to 3 PLC	0.8	0.5
4 PLC to 5 PLC	0.6	0.4
6 PLC to 10 PLC	0.5	0.3
20 PLC to 30 PLC	0.2	0.2
40 PLC to 50 PLC	0.2	0.1
60 PLC to 90 PLC	0.1	0.05

*4 1 µs is an unspecified accuracy.

Range multiplier of range error	Range	Multiplier ^{*5}
	100 mV	×20 (×100)
	1000 mV	×2 (×10)
	10 V	×1 (×1)
	100 V	×2 (×10)
	1000 V	×1 (×1)

*5 Integration time 200 µs to 10 ms for multipliers in the parentheses

Noise rejection: Between GUARD and LO terminals, at unbalanced impedance of 1 k Ω

late metica time.	Effective CN	NMR	
Integration time	50/60 Hz±0.07 %	DC	50/60 Hz±0.07 %
10 ms or less	90 dB	140 dB	0 dB
1 PLC or more	150 dB	140 dB	60 dB

Resistance Measurement

	_ Maximum			F	lesolutio		Measurement	Open	
	Range	display	8½	7½	6½	5½	41⁄2	current	circuit voltage
	10 Ω	11.999999 Ω	-	1μΩ	10 μΩ	100 μΩ	1 mΩ	10 mA	13 V
	100 Ω	119.999999 Ω	1 μΩ	10 μΩ	100 μΩ	1 mΩ	10 mΩ	10 mA	13 V
	1000 Ω	1199.99999 Ω	10 μΩ	100 μΩ	1 mΩ	10 mΩ	100 mΩ	1 mA	13 V
Lliab	10 kΩ	11.9999999 kΩ	100 μΩ	1 mΩ	10 mΩ	100 mΩ	1Ω	1 mA	17 V
High- Power	100 kΩ	119.999999 kΩ	1 mΩ	10 mΩ	100 mΩ	1Ω	10 Ω	100 µA	17 V
TOWER	1000 kΩ	1199.99999 kΩ	10 mΩ	100 mΩ	1Ω	10 Ω	100 Ω	10 µA	17 V
	10 MΩ	11.999999 MΩ	-	1Ω	10 Ω	100 Ω	1 kΩ	1 µA	17 V
	100 MΩ	119.99999 MΩ	-	10 Ω	100 Ω	1 kΩ	10 kΩ	100 nA	16 V
	1000 MΩ	1199.9999 MΩ	-	100 Ω	1 kΩ	10 kΩ	100 kΩ	10 nA	16 V
	10 Ω	11.999999 Ω	-	1μΩ	10 μΩ	100 μΩ	1 mΩ	10 mA	5 V
	100 Ω	119.99999 Ω	-	10 μΩ	100 μΩ	1 mΩ	10 mΩ	1 mA	5 V
	1000 Ω	1199.9999 Ω	-	100 μΩ	1 mΩ	10 mΩ	100 mΩ	1 mA	5 V
low-	10 kΩ	11.999999 kΩ	-	1 mΩ	10 mΩ	100 mΩ	1Ω	100 µA	5 V
Low- Power	100 kΩ	119.99999 kΩ	-	10 mΩ	100 mΩ	1Ω	10 Ω	10 µA	5 V
i owei	1000 kΩ	1199.9999 kΩ	-	100 mΩ	1Ω	10 Ω	100 Ω	1 µA	5 V
	10 MΩ	11.999999 MΩ	-	1Ω	10 Ω	100 Ω	1 kΩ	100 nA	5 V
	100 MΩ	119.99999 MΩ	-	10 Ω	100 Ω	1 kΩ	10 kΩ	10 nA	5 V
	1000 MΩ	1199.9999 MΩ	-	100 Ω	1 kΩ	10 kΩ	100 kΩ	10 nA	16 V

Maximum input voltage: Between measurement terminals: ±350 V peak GUARD-chassis ±420 V peak GUARD-LO terminal ±100 V peak

4-Wire Resistance Measurement

Accuracy: Relative accuracy with the integration time of 100 PLC ± (ppm of reading + ppm of range)

	Danga	24 hours	90 days ^{*6}	1 year ^{*6}
	Range	Tcal ± 1 °C	Tcal ± 5 °C	
	10 Ω	5+10	12+20	14+20
	100 Ω	5+2	10+5	12+5
	1000 Ω	3+2	8+5	10+5
Lliab	10 kΩ	2+0.2	6+0.5	8+0.5
High- Power	100 kΩ	2+0.2	6+0.5	8+0.5
Power	1000 kΩ	10+1	12+1	14+1
	10 MΩ	50+5	50+5	50+5
	100 MΩ	500+10	500+10	500+10
	1000 MΩ	0.5 %+10	0.5 %+10	0.5 %+10
	10 Ω	5+10	12+20	14+20
	100 Ω	5+10	12+20	14+20
	1000 Ω	3+2	8+5	10+5
Low-	10 kΩ	3+2	10+5	12+5
	100 kΩ	10+2	12+5	14+5
Power	1000 kΩ	50+5	50+5	50+5
	10 MΩ	500+50	500+50	500+50
	100 MΩ	0.5 %+50	0.5 %+50	0.5 %+50
	1000 MΩ	0.5 %+10	0.5 %+10	0.5 %+10

*6 Within 24 hours after last INT CAL, ±1 °C, Tcal ±5 °C (MATH NULL, fixed range)

Add 3.1 ppm of reading additional error for ADC traceability to Japan's national standard.

Temperature coefficient: ± (ppm of reading + ppm of range)/°C

-			
	Danas	Temperature	e coefficient
	Range	Without INT CAL	With INT CAL
	10 Ω	3+3	1+3
	100 Ω	3+1	1+1
	1000 Ω	2+1	1+1
	10 kΩ	2+0.1	1+0.1
High-Power	100 kΩ	2+0.1	1+0.1
	1000 kΩ	2+0.1	1+0.1
	10 MΩ	20+0.1	5+0.1
	100 M Ω	100+1	50+1
	1000 MΩ	1000+1	500+1
	10 Ω	3+3	1+3
	100 Ω	3+3	1+3
	1000 Ω	2+1	1+1
	10 kΩ	2+1	1+1
Low-Power	100 kΩ	2+1	1+1
	1000 kΩ	10+1	5+1
	10 MΩ	100+10	25+10
	100 M Ω	1000+10	250+10
	1000 MΩ	1000+1	500+1

Additional error: Add the following additional error for integration time other than 100 PLC.⁷

Integration time	Gain error	Range error
Integration time	ppm of reading	ppm of range
2 µs to 10 µs	2000	1500
20 µs to 100 µs	200	150
200 µs to 1 ms	30	30
2 ms to 10 ms	10	10
1 PLC to 10 PLC	1	0.6
20 PLC to 50 PLC	0.2	0.2
60 PLC to 90 PLC	0.1	0.1

*7 1 μs is an unspecified accuracy.

Range multiplier of range error

	Range	Multiplier '8
	10 Ω	×20 (×100)
High-Power	100 Ω to 1000 Ω	×5 (×10)
	10 kΩ to 1000 MΩ	×1 (×1)
	10 Ω to 100 Ω	×20 (×100)
Low-Power	1000 Ω to 100 MΩ	×5 (×10)
	1000 MΩ	×1 (×1)

*8 Integration time 200 µs to 10 ms for multipliers in the parentheses

 $4~\text{W}\Omega$ check function ON: Add 5 ppm gain error.

 $\Omega\text{-}COMP$ function ON: Add 2 ppm gain error for 100 $k\Omega$ and 5 ppm gain error for 1000 $k\Omega.$

2-Wire Resistance Measurement

Accuracy: Add 0.2 Ω offset error to ppm of range of 4-wire resistance measurement (4 W Ω) accuracy.

Temperature coefficient (Auto-zero OFF):

Add the following addition error (ppm of range)/ $^{\circ}$ C to the temperature coefficient of 4-wire resistance measurement (4 W Ω).

	Range	Additional error ppm of range/°C
	10 Ω	50
High-Power	100 Ω to 1000 Ω	5
	10 kΩ to 1000 MΩ	1
	10 Ω to 100 Ω	50
Low-Power	1000 Ω to 100 MΩ	5
	1000 MΩ	1

DC Current Measurement

Range/maximum display resolution/input impedance/over input protection

Range	Maximum		Reso	lution		Input	Over input
nanye	display	7½	6½	51/2	41⁄2	impedance	protection
100 nA	119.9999 nA	-	100 fA	1 pA	10 pA	1010 k Ω or less	
1000 nA	1199.9999 nA	100 fA	1 pA	10 pA	100 pA	105 k Ω or less	
10 µA	11.999999 µA	1 pA	10 pA	100 pA	1 nA	10.1 kΩ or less	1.25 A/250 V
100 µA	119.99999 µA	10 pA	100 pA	1 nA	10 nA	1.01 kΩ or less	fast-blow
1000 µA	1199.9999 µA	100 pA	1 nA	10 nA	100 nA	102 Ω or less	fuse
10 mA	11.999999 mA	1 nA	10 nA	100 nA	1 µA	12 Ω or less	protection
100 mA	119.99999 mA	10 nA	100 nA	1 µA	10 µA	3 Ω or less	
1000 mA	1199.9999 mA	100 nA	1 µA	10 µA	100 µA	2 Ω or less	

Accuracy: Relative accuracy with the integration time of 100 PLC \pm (ppm of reading+ ppm of range)

Range	24 hours ^{*2}	90 days ^{*9}	1 year ^{'9}
nange	Tcal ± 1 °C	Tcal ±	±5°C
100 nA	10+400	25+400	25+400
1000 nA	10+40	15+40	20+40
10 µA	5+10	15+20	20+20
100 µA	5+10	15+20	20+20
1000 µA	5+10	15+20	20+20
10 mA	10+10	15+20	20+20
100 mA	20+10	25+20	30+20
1000 mA	100+10	100+20	110+20

*9 Within 24 hours after last INT CAL, ±1 °C, Tcal ± 5 °C (MATH NULL, fixed range)

Add 4 ppm of reading additional error for ADC traceability to Japan's national standard.

Temperature coefficient: ± (ppm of reading + ppm of range)/°C

Range	Temperature coefficient				
nange	Without INT CAL	With INT CAL			
100 nA	10+200	2+50			
1000 nA	10+20	2+5			
10 µA	2+4	2+1			
100 µA	5+3	2+1			
1000 µA	5+2	2+1			
10 mA	10+2	5+1			
100 mA	20+2	5+1			
1000 mA	20+3	10+2			

Additional error: Add the following additional errors for integration time other than 100 PLC.¹⁰

Integration time	Gain error	Range error
	ppm of reading	ppm of range
2 µs to 10 µs	2000	2000
20 µs to 100 µs	200	1200
200 µs to 1 ms	30	1200
2 ms to 10 ms	10	800
1 PLC to 10 PLC	1	10
20 PLC to 50 PLC	0.2	4
60 PLC to 90 PLC	0.1	2

*10 1 μs is an unspecified accuracy.

Range multiplier of	Range	Multiplier
range error	100 nA	×50
	1000 nA	×5
	10 µA to 1000 mA	×1

AC Voltage Measurement (7482 only)

Range/maximum display/resolution/input impedance/maximum allowable voltage True RMS

Range	Maximum		Resolut	tion			out	Maximum				
nanye	display	6 ½	5 1/2 4 1/2		impe	dance	allowable voltage					
10 mV	11.9999 mV	-	100 n\	V	1 µV	1 MΩ:	±10 %					
100 mV	119.9999 mV	100 nV	1 μ\	V	10 µV	170 pF	or less	±1000 V peak between input HI				
1000 mV	1199.999 mV	1 µV	10 µ\	V	100 µV							
10 V	11.99999 V	10 µV	100 µ\	V	1 mV	1 MΩ	±3 %	and LO terminals				
100 V	119.9999 V	100 µV	1 m	١V	10 mV	170 pF	or less					
700 V	799.999 V	1 mV	10 m	١V	100 mV							
ccuracy	/: ± (% of re	ading+ 9	% of ra	ange	e) with t	he inte	gration	time of 100				
	PLC (1 yea	ar, Tcal ±	± 1 °C)									
	Specified	with sin	e wave	e int	put of 5	% or r	nore of	full scale and				
Specified with sine wave input of 5 % or more of full scale and												
	1,107 1/1-7	orloce	andw	vithi	1×10 ⁷ VHz or less, and within 24 hours after INT CAL.							
	1×107 VHz	or less,	and w	vithi	in 24 ho	urs aft	er INT C	CAL.				
	1×10 ⁷ VHz	or less,	and w	vithi	in 24 ho	urs aft	er INT C	CAL.				
or AC	1×10 ⁷ VHz	or less,	and w	vithi	in 24 ho	urs aft	er INT (CAL.				
or AC Range	1×10 ⁷ VHz	or less, 20 Hz to			in 24 ho Hz to 100 H		er INT C					
			o 40 Hz	40		z 100 H						
Range	10 Hz to 20 Hz	20 Hz to	0 40 Hz 0.25	40 I 0	Hz to 100 H	z 100 H	lz to 10 kHz	: 10 kHz to 50 kHz				
Range 10 mV	10 Hz to 20 Hz 0.7+0.3	20 Hz to 0.2+0	0 40 Hz 0.25 0.02	40 I 0 0	Hz to 100 H).08+0.25	z 100 H	lz to 10 kHz 03+0.25	10 kHz to 50 kHz 0.15+0.25				
Range 10 mV 100 mV	10 Hz to 20 Hz 0.7+0.3 0.7+0.02	20 Hz to 0.2+0 0.2+0	0 40 Hz 0.25 0.02 0.02	40 I 0 0	Hz to 100 H).08+0.25).08+0.02	z 100 H 0.0 0.0	lz to 10 kHz 03+0.25 02+0.02	10 kHz to 50 kH 0.15+0.25 0.15+0.04				
Range 10 mV 100 mV 1000 mV	10 Hz to 20 Hz 0.7+0.3 0.7+0.02 0.7+0.02	20 Hz to 0.2+0 0.2+0 0.2+0	0 40 Hz 0.25 0.02 0.02 0.02	40 I 0 0 0	Hz to 100 H 0.08+0.25 0.08+0.02 0.08+0.015	z 100 H 0.0 0.0 0.0	Iz to 10 kHz 03+0.25 02+0.02 02+0.015	 10 kHz to 50 kH 0.15+0.25 0.15+0.04 0.15+0.04 				
Range 10 mV 100 mV 1000 mV 10 V	10 Hz to 20 Hz 0.7+0.3 0.7+0.02 0.7+0.02 0.7+0.02	20 Hz to 0.2+(0.2+(0.2+(0.2+(0 40 Hz 0.25 0.02 0.02 0.02 0.02 0.02	40 I 0 0 0.1	Hz to 100 H 0.08+0.25 0.08+0.02 0.08+0.015 075+0.015	z 100 F 0.0 0.0 0.0 0.0	lz to 10 kHz 03+0.25 02+0.02 02+0.015 15+0.015	10 kHz to 50 kH 0.15+0.25 0.15+0.04 0.15+0.04 0.15+0.04				
Range 10 mV 100 mV 1000 mV 100 V	10 Hz to 20 Hz 0.7+0.3 0.7+0.02 0.7+0.02 0.7+0.02 0.7+0.02	20 Hz tc 0.2+(0.2+(0.2+(0.2+(0.2+(0.2+(0 40 Hz 0.25 0.02 0.02 0.02 0.02 0.02 0.02	40 I 0 0 0.0 0.0	Hz to 100 H 0.08+0.25 0.08+0.02 0.08+0.015 075+0.015 075+0.015	z 100 H 0.0 0.0 0.0 0.0 0.0	lz to 10 kHz 03+0.25 02+0.02 02+0.015 15+0.015 15+0.015	10 kHz to 50 kH 0.15+0.25 0.15+0.04 0.15+0.04 0.15+0.04 0.15+0.04				
Range 10 mV 100 mV 1000 mV 10 V 100 V 700 V	10 Hz to 20 Hz 0.7+0.3 0.7+0.02 0.7+0.02 0.7+0.02 0.7+0.02 0.7+0.02 0.7+0.03	20 Hz tc 0.2+0 0.2+0 0.2+0 0.2+0 0.2+0 0.2+0 0.2+0	0 40 Hz 0.25 0.02 0.02 0.02 0.02 0.02 0.02 0.02	40 I 0 0 0.0 0.0	Hz to 100 H 0.08+0.25 0.08+0.02 0.08+0.015 075+0.015 075+0.015 0.08+0.02	z 100 H 0.0 0.0 0.0 0.0 0.0	lz to 10 kHz 03+0.25 02+0.02 02+0.015 15+0.015 15+0.015 05+0.02	10 kHz to 50 kH 0.15+0.25 0.15+0.04 0.15+0.04 0.15+0.04 0.15+0.04 0.15+0.04				
Range 10 mV 100 mV 1000 mV 100 V 100 V 700 V Range	10 Hz to 20 Hz 0.7+0.3 0.7+0.02 0.7+0.02 0.7+0.02 0.7+0.02 0.7+0.02 0.7+0.03 50 kHz to 100 kHz	20 Hz to 0.2+0 0.2+0 0.2+0 0.2+0 0.2+0 0.2+0 0.2+0 100 kHz to	0 40 Hz 0.25 0.02 0.02 0.02 0.02 0.02 0.02 0.02	40 I 0 0 0.0 0.0	Hz to 100 H 0.08+0.25 0.08+0.02 0.08+0.015 075+0.015 075+0.015 0.08+0.02	z 100 H 0.0 0.0 0.0 0.0 0.0	lz to 10 kHz 03+0.25 02+0.02 02+0.015 15+0.015 15+0.015 05+0.02	10 kHz to 50 kH 0.15+0.25 0.15+0.04 0.15+0.04 0.15+0.04 0.15+0.04 0.15+0.04				
Range 10 mV 100 mV 1000 mV 100 V 700 V Range 10 mV	10 Hz to 20 Hz 0.7+0.3 0.7+0.02 0.7+0.02 0.7+0.02 0.7+0.02 0.7+0.03 50 kHz to 100 kHz 0.7+0.3	20 Hz tc 0.2+(0.2+(0.2+(0.2+(0.2+(0.2+(100 kHz to 8+(0 40 Hz 0.25 0.02 0.02 0.02 0.02 0.02 0.02 0.02	40 I 0 0 0.0 0.0	Hz to 100 H 0.08+0.25 0.08+0.02 0.08+0.015 075+0.015 0.08+0.02 kHz to 500 kH	z 100 H 0.0 0.0 0.0 0.0 0.0 1z 500 k	Iz to 10 kHz 03+0.25 02+0.02 02+0.015 15+0.015 15+0.015 05+0.02 Hz to 1 MHz -	10 KHz to 50 KH 0.15+0.25 0.15+0.04 0.15+0.04 0.15+0.04 0.15+0.04 0.15+0.04 1 MHz to 2 MHz -				

*11 Reference value

0.25+0.08

0.3+0.2

For AC + DC

100 V

700 V

Range	10 Hz to 20 Hz	20 Hz to 40 Hz	40 Hz to 100 Hz	100 Hz to
10 mV	0.4+0.3	0.15+0.25	0.06+0.25	
100 mV	0.4+0.02	0.15+0.02	0.06+0.02	
1000 mV	0.4+0.02	0.15+0.02	0.06+0.015	Same as the
10 V	0.4+0.02	0.15+0.02	0.055+0.015	accuracies of AC
100 V	0.4+0.02	0.15+0.02	0.055+0.015	
700 V	0.4+0.03	0.15+0.02	0.06+0.02	

1.5+0.6

2.5+1"

0.5+0.5

If the DC component exceeds 10 % of the AC component, the following error is added to each range.

Range	10 mV	100 mV	1000 mV to 700 V
Additional error	0.1+3	0.1+0.2	0.1+0.1

Temperature coefficient: Additional error from Tcal, specified within \pm 1 °C after INT CAL execution.

(1/10 of measurement accuracy including additional error)/°C at each frequency in each range

Crest factor:5 (FILTER SLOW, MID)

 Crest factor additional error:±(% of range)

 Crest factor
 1 to 2
 2 to 3
 3 to 4
 4 to 5

 Additional error
 0
 0.15
 0.25
 0.40

Settling time: Time to reach 0.1 % of input step FAST 25 ms, MID 120 ms, SLOW 1000 ms

Low frequency additional error: ±(% of reading)

FILTER	200 Hz to 500 Hz	500 Hz to 1 kHz	1 kHz to 2 kHz	2 kHz to 5 kHz	5 kHz to 10 kHz
SLOW	0	0	0	0	0
MID	0.15	0.015	0	0	0
FAST	-	-	0.2	0.05	0.01

AC Current Measurement (7482 only)

Range/maximum display/resolution/input impedance/over input protection True RMS

Range	Maximum		Resolution		Input impedance	Over input
nange	display	6 ½	5 ½	4 1⁄2	input impedance	protection
100 µA	119.9999 µA	100 pA	1 nA	10 nA	1.01 kΩ or less	
1000 µA	1199.999 µA	1 nA	10 nA	100 nA	102 Ω or less	1.25 A/250 V
10 mA	11.99999 mA	10 nA	100 nA	1 µA	12 Ω or less	fast-blow fuse
100 mA	119.9999 mA	100 nA	1 µA	10 µA	3 Ω or less	protection
1000 mA	1199.999 mA	1 µA	10 µA	100 µA	2 Ω or less	

Accuracy: \pm (% of reading+ % of range) with the integration time of 100 PLC (1 year, Tcal \pm 1 °C)

Specified with sine wave input of 5% or more of full scale and within 24 hours after INT CAL.

(For the 100 μA range, the accuracy is specified with sine wave input of 10 % or more up to 1 kHz.)

For AC

1 01 / 10				
Range	10 Hz to 20 Hz	20 Hz to 45 Hz	45 Hz to 100 Hz	100 Hz to 5 kHz
100 µA to 100 mA	0.7+0.02	0.2+0.02	0.08+0.02	0.03+0.02
1000 mA	0.7+0.02	0.2+0.02	0.08+0.02	0.1+0.02

For AC + DC

Range	10 Hz to 20 Hz	20 Hz to 45 Hz	45 Hz to 100 Hz	100 Hz to 5 kHz		
100 µA to 100 mA	0.4+0.02	0.15+0.02	0.06+0.02	0.03+0.02		
1000 mA	0.4+0.02	0.15+0.02	0.08+0.02	0.1+0.02		

If the DC component exceeds 10 % of the AC component, "0.1 % of reading+ 0.2 % of range" is added to each range as additional error.

Temperature coefficient: Additional error from Tcal, specified within \pm 1 °C after INT CAL execution.

(1/10 of measurement accuracy including additional error)/°C at each frequency in each range

Crest factor:5 (FILTER SLOW, MID)

Crest factor	1 to 2	2 to 3	3 to 4	4 to 5
Additional error	0	0.15	0.25	0.40

Settling time: Time to reach 0.1 % of input step

FAST 25 ms, MID 120 ms, SLOW 1000 ms

Low frequency additional error: ±(% of reading)

FILTER	200 Hz to 500 Hz	500 Hz to 1 kHz	1 kHz to 2 kHz	2 kHz to 5 kHz
SLOW	0	0	0	0
MID	0.15	0.015	0	0
FAST	-	-	0.2	0.05

Frequency/Period Measurement (7482 only)

Measurement range/input signal range/input impedance

	AC voltage input ^{*12}	AC current input			
Frequency measurement range	1 Hz to 10 MHz	1 Hz to 10 kHz			
Period measurement range	1 s to 100 ns	1 s to 100 µs			
Input signal range	5 mVrms to 700 Vrms	10 µArms to 1 Arms			
Input impedance	Refer to the input impedance described in AC voltage measurement and AC current measurement sections.				

*12 The input signal range is from 50 mVrms when the frequency is 1 MHz or higher.

Accuracy

Measurement range		± (% of reading)	
Frequency	Period	Square wave	Sine wave
1 Hz to 10 Hz	1 s to 100 ms	0.05	1
10 Hz to 100 Hz	100 ms to 10 ms	0.02 0.1	
100 Hz to 10 MHz	10 ms to 100 ns	0.01	

Gate time/display digits/maximum display

Gate time	Display digits	Maximum display
100 µs	3 digits	999
1 ms	4 digits	999 9
10 ms	5 digits	999 99
100 ms	6 digits	999 999
1 s	7 digits	999 999 9

Trigger level: Can be set to ± 500 % of range (in 20 % steps). However, for the 700 VAC range, the trigger level is set to ± 100 % of 1000 V (in 20 % steps).

The trigger level setting is valid for frequency below 1 MHz.

Ratio Measurement

Ratio	Input voltage/reference voltage
Input voltage	Between DCV HI and LO terminals
Reference voltage	(Between 4WΩHI and LO terminals) -
	(Between 4WΩLO and LO terminals)
Reference	DCV 100 mV to 10 V (auto range only)
measurement range	Dev roo mv to ro v (auto range omy)

Accuracy:

,	
Ratio measurement	± (Input measurement error + Reference measurement
accuracy	error)
Input measurement	Total range error of DCV input signal measurement × 1
error	
Reference	Total range error of DCV reference signal measurement
measurement error	× 1.5

Integration Time

Integration T	ime	
The integration tim	ne can be set as follo	ows:
1 µs to 10 µs:	1 µs step	
20 µs to 100 µs:	10 µs step	
200 µs to 1 ms:	100 µs step	
2 ms to 10 ms:	1 ms step	
1 PLC to 10 PLC:	1 PLC step	
10 PLC to 100 PLC	C: 10 PLC step	
4½-digit display	1 µs to 100 PLC	
51/2-digit display	100 µs to 100 PLC)
6½-digit display	1 ms to 100 PLC	
7½-digit display	1 PLC to 100 PLC	
8½-digit display	10 PLC to 100 PLC	C
PLC: Power Line C	Cycle	
10 PLC is repeated	d in case of 20 PLC o	or longer.
Computing O	norationa	
Computing O Digital filter:	perations	
Smoothing	Obtains the moving	average of measurement data of a
	specified smoothing	g count.
	Smoothing count: 2	to 100
Averaging	Obtains the average	e of measurement data of a specified
	averaging count.	
	Averaging count: 2	to 100
Format:		
Scaling		
	D-Y	
	$R = \frac{D - Y}{X} \times Z$	(X, Y, Z: constant)
% deviation		
	$R = \frac{D - X}{ X } \times 100$	(%)
	X	
Delta	$R = D_{t} - D_{t-1}$	(difference from the previous
		measured value)
dB conversion	R = 20 log ₁₀ D/X	(dB)
	0101	
RMS	N	
	$\mathbf{R} = \frac{1}{2} \sum \mathbf{D}^2$	
	$R = \left \frac{1}{N} \sum_{K=1}^{N} D_{K}^{2} \right $	
	√ ^K =1	
dBm conversion		
	D ² /X	

R

$$= 10 \log_{10} \frac{D^2 / X}{10^{-3}} (\text{dBm})$$

R: dBm conversion value based on 1 mW (= 0 dBm) D: voltage measured value (V) X: reference resistance value (Ω)

Resistance value temperature compensation

$$R_{20} = \frac{R_{X}}{1+0.00393 \text{ (T-20)}} \times \frac{1000}{L} \text{ (}\Omega/\text{km)}$$

R _x : Me	asured r	esistan	ce value of c ce value at te at measurer	mperatu	ire of X °C	(Ω)
Pt sensor tempera	ture mea	asurem	ent: JIS C16	04-1997	(ITS90)	
			JP area	UPPE	R < D	
Comparator:	Operati	on N	MID area	LOWE	$R \le D \le UP$	PER
		L	OW area	D < L(OWER	
	UPPER	-9.99	ng range 999999 E+5 ⁻ 999999 E+5 ⁻			
	PASS o	r FAIL i etting i	ılt display s displayed a s available in areas.			ach of UP,
Statistic operation:	RN Rmax Rmin Rucl Rlcl	Maxim Minimu Upper	er of samples um value, um value, Control Line Control Line	Rp-p Rσ Rave+3	Dispersio Standard βRσ	
Null operation:	subtrac values.	ts the n Null co	measured va null value fron rrection is av nent range.	n the fol	lowing mea	asured
Memory function:	500,000) data fo on sett	nts Measure or the Option ing memory clock)	+06)		
Trigger function:	Trigger	source	IMMEDIATI BUS, LEVE			RNAL,
Interface Fun GPIB interface:	ction					
Command	d system		Compliant 1	to IEEE 4	488.2-1987	7
Connecto	-		Amphenol 2	24 pin		
Interface f			SH1, AH1,		SB1 BI1	
interfacer	unetion		PP0, DC1,			
USB interface:						
Standard			Compliant t	to USB 2	2.0 Full-Sp	eed
Connecto	r		Type B		I.	
LAN interface (Opt	tion +06)	1				
Standard			Compliant f	to IEEE 8	302.3	
Transmiss	sion		10Base-T,	100Base	e-TX	
Connecto	r		RJ-45			
Front panel USB h		(Optior				
	-		class device	s		
Measuren	•	•				
Standard		. ,	Compliant 1	to USB 2	2.0 Full-Sp	eed
Connecto	r		Туре А		· ··· -P	
I the second designed in a last			0	In		

Input terminals:

External control signals: Connector Trigger input signal

BNC connector TTL level, positive/negative pulse selectable TLL level, negative pulse Complete output signal Comparator output signal Open collector/pull-up selectable PASS/FAIL output selectable

input by remote control

Switchable between front input and rear

General Specific	ations
Operating environment	t: Temperature: 0 °C to +50 °C (7481)
	0 °C to +45 °C (7482)
	(Performance guaranteed between 0 °C and +40 °C) Relative humidity: 85 % or less, no condensation (65 % or less no condensation for resistance measurement ranges: 1 M Ω , 10 M Ω , 100 M Ω , 1000 M Ω , current measurement 100 nA range)
Storage environment:	Temperature: -25 °C to +70 °C Relative humidity: 85 % or less, no condensation
Warm-up time: Display Range switching Input method	4 hours or more to meet the specifications 256 × 64 dot-matric VFD Automatic and manual Floating and guarded

Maximum allowable applied voltage

					4WΩHI
				HI	350 V
			4WΩLO	350 V	350 V
		LO	350 V	1000 V	350 V
	GUARD	100 V	450 V	1000 V	450 V
Chassis	420 V	420 V	770 V	1000 V	770 V
* Do not apply more than 1000 V between the same terminals on the					

* Do not apply more than 1000 V between the same terminals on the front and the rear.

Measurement method: Integration

Power	supp	ly:
-------	------	-----

AC power supply 100 V/120 V/220 V/240 V (User selectable)

Option number	Standard	OPT. 32	OPT. 42	OPT. 44
Power voltage	100 V	120 V	220 V	240 V

Use a power cable and a fuse that are compliant with the safety standard when changing the power supply voltage.

Line frequency:	50 Hz/60 Hz
Power consumption:	42 VA or less
Dimensions:	Approx. 424 (W) × 88 (H) × 450 (D) mm
Mass:	7481 9 kg or less
	7482 10 kg or less
Safety:	Compliant with IEC61010-1 Ed.3 Measurement CAT II
EMC:	EN61326-1 class A

Supplied accessories

Name	Model	Quantity
Power cable (JIS 2 m)	A01402	1
Input cable (test probe 1 m)	CC010001	1
Alligator clip adapter (for CC010001)	CC015001	1
Current terminal protection fuse	DFS-AN1R25A-1	1
Power fuse	DFT-AA1A-1	1
EMI clamp	DEE-100345-1	1

Optional accessories

Name	Model
Input cable (for 4-wire measurement, with guard)	A01005
Input cable (for 4-wire measurement)	A01006
Input cable (banana- alligator)	A01035
Input cable (test probe 1 m)	CC010001
Alligator clip adapter (for CC010001)	CC015001
Front handle set 2U	CC028002
Rack mount set EIA 2U	CC024002
Rack mount set JIS 2U	CC022002

(The front handle set and the rack mount set can be used in combination.)

Option

Function	Model
LAN interface Front panel USB host port Internal memory 500,000 data	7481+06(Factory option) 7482+06(Factory option)

• Please read through the operation manual carefully before using the product.

• All specifications are subject to change without notice.



E-mail : kcc@adcmt.com URL : http://www.adcmt.com

Head Office (R&D Center)

77-1, Miyako Namegawa-machi, Hiki-gun, Saitama 355-0812, Japan Phone: +81-493-56-4433 Fax: +81-493-57-1092

East Branch (Sales Dept.)

Okabe-building, 3-515, Onari-cho, Omiya-ku, Saitama-shi, Saitama 330-0852, Japan Phone: +81-48-651-4433 Fax: +81-48-651-4432